

---

**GRANDSTREAM NETWORKS**

Firmware Release Notes  
Firmware Version 1.0.6.9  
Product Name: GXP2170  
Date: January 14, 2016

**CHANGES SINCE FIRMWARE RELEASE 1.0.6.5****ENHANCEMENT**

- Improved DND indication to cover transparent background
- Added support to display date time/weather when RIGHT VPK panel is empty
- Added support to configure whether to show label background on VPK
- Added support to show long label on VPK
- Added support to hide softkeys on main page
- Added secondary softkey FIRST to quickly return to VPK page one
- Added NewCall softkey on call screen for user to initiate new phone call
- Marked softkey EndCall to RED style

**BUG FIXES**

- Fixed Device BLF is not updated correctly issue
- Fixed Phone randomly doesn't send voice when using Plantronics EHS CS540A headset with APV-63 EHS adapter
- Fixed Line key LEDs don't provide visual indications of Shared call appearances
- Fixed Device fails to displays BLF and Call park subscription status
- Fixed The mode of EXT is changed to Speed Dial after reset on web
- Fixed DND indication unfriendly issue
- Fixed Device work abnormal after press TRANSFER key then press NewCall softkey
- Fixed The Back softkey at the Bluetooth Scan screen cannot switch to Home softkey
- Fixed Device possible crash when drawing DND screen

=====

Firmware Release Notes  
Firmware Version 1.0.6.5  
Product Name: GXP2170  
Date: December 18, 2015

**CHANGES SINCE FIRMWARE RELEASE 1.0.6.2****ENHANCEMENT**

- Added VPK support for eventlist auto-provision. If there are more BLFs in the eventlist than idle VPK keys, extra BLFs will be auto-provisioned to EXT board
- Improved the display format of missed calls
- Added display of extension Forward All in idle screen
- Added German language input in all configuration fields where the user is required to enter alphanumeric input
- Added 12 lines support (with 6 accounts)
- Added "None" mode for VPK

**BUG FIXES**

- Fixed LCD displays abnormal after changing language on the VPK editing screen
- Fixed Broadsoft Silent Alerting feature doesn't work

- Fixed GUI crashes after downloading a large XML application file
- Fixed The device calls the wrong number after entering number in onhook dialing screen then pressing MPK
- Fixed The device does not send DHCP DISCOVER after factory reset
- Fixed LCD doesn't have prompt when adding an invalid local group
- Fixed Obtaining the wallpaper from USB flash drive requires reboot to take effect
- Fixed Voicemail VPK is invalid after configuring its value
- Fixed The HOLD screen displays abnormal
- Fixed LCD does not display the RESUME softkey when the call is on hold
- Fixed LCD does no display MENU mode on editing screen of VPK
- Fixed Device fails to set LINE to Menu mode
- Fixed Device fails to download wallpaper after repeating downloading and uploading
- Fixed LCD does not display softkey-MPK in time when setting the MPK on the weather or currency screen
- Fixed The editing screen of VPK is displayed wrong after setting VPK on LCD
- Fixed The label of LINE 6 is displayed abnormal after disabling Bluetooth Hands-free mode
- Fixed Device speed dial with Bluetooth Hands-free account after setting VPK account to account 6
- Fixed The Save and Apply button on VPK web page does not work for other web pages
- Fixed LCD pops up prompt after pressing VPK which is not configured
- Fixed The Save and Apply button on VPK web page works abnormal
- Fixed LCD is displayed abnormally when adding the 47<sup>th</sup> and 48<sup>th</sup> VPK
- Fixed The device is displaying extra currency entries when less than 5 entries are queried
- Fixed Currently page does not update periodically